


Bygel på radiokort när LF saknas

10.2 Componentside



Componentside 776-5

SUBJECT TO CHANGE WITHOUT NOTICE

DATE: 6-8-98	SIGN: PH	2	NIROS TELECOMMUNICATION A/S HIRSEMARKEN 5, 3520 FARUM
DATE: 28-7-98	SIGN: PH	3	
DATE: 8-12-98	SIGN: HEK	4	
DATE: 5-5-00	SIGN: HEK	5	
DATE: 2-10-00	SIGN: HEK	6	Radioboard TRX3001B
DATE:	SIGN:	8	
DRAWING NO: 0-3000-05-6			PCB NO: 776-5

SMPLEX	UNIT NO: 3004
25KHz	UNIT NO: 3005
12,5KHz	UNIT NO: 3014
SW	
DUPLEX	UNIT NO: 3204
25KHz	UNIT NO: 3205
12,5KHz	UNIT NO: 3214
SW	

File/Reference	Prepared	Date	Revised by	Revised date	Revision No.	Approved
Manual for TRX3001	TN	07-03-01	TN	03-10-00	3	PA